

United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

August 27, 2010

Mr. Ed Peresie Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Mr. Steve Hepler Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject:

USS Reference Number: 10-0398 ACHD Reference Number: 12983 SCOT Plant Incinerator USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Plant Manager Clairton Works

> RECEIVED SEP 0 8 20m 3AP20

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 10-0398
 ACHD Reference Number: 12983
- 2. Date & Time of Breakdown: Date: 08/27/10 Time: 1040 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: SCOT Plant Incinerator
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: The SCOT Plant Incinerator was unavailable for service when it lost combustion.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)
 Elevated H2S at the incinerator stack.
 - B. B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). H2S is an eye, nose, and throat irritant.
 - C. Amount of each type emitted (or likely to be emitted). Light to Moderate
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 The incinerator was re-lit and normal operations resumed.
- 10. Facility back in operation Date: 08/27/10 Time: 1105 hours

Signature (len)/2./hus Date 8-30-10

Coleen M. Davis

Senior Environmental Control Engineer Phone: 412-233-1015